

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

AMENDMENTS TO THE SPECIFICATION

The paragraph starting on page 5 at line 6 is amended as follows:

Underfill resin ~~20~~ 22 is then injected between semiconductor chip 14 and substrate 11, and heat sink 21 is applied to the side of substrate 11 that is opposite the side on which semiconductor chip 14 is mounted. Underfill resin ~~20~~ 22 adheres well to the surfaces of substrate 11 and semiconductor chip 14 because both surfaces have been effectively cleaned.